


# United Plant Guard Workers of America (UPGWA)



Local 66

P.O. Box 1020, Piketon, Ohio 45661

70-7002

D509

63FR 24832

M. Hoan

May 5, 1998

(1)

Chief, Rules Review & Directives Branch  
Office of Administration  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

June 16, 1998

1998 JUN 19 PM 4:22  
RULES & DIR. BRANCH  
US NRC

RECEIVED

Dear Office of Administration NRC:


This letter is to address United States Enrichment Corporation (USEC) application for renewal of the Portsmouth Gaseous Diffusion Plant based on USEC's previous application, as revised through Revision 19 dated April 15, 1998.

Since the first application and oversight responsibilities started on March 3, 1997, USEC has had many revisions to the complete program and thousands of RAC's to make changes to their original commitments on how USEC was to operate the Portsmouth facility. USEC has been to enforcement conferences, pre-decisional conferences, suspending work due to violations, notice of violations, NIOSH findings, OSHA findings, and the issue of the "Chilling Effects".

Since March 3, 1997 the business of the enrichment of uranium is a new venture for the NRC administration when it comes to the Gaseous Diffusion Plants. The issue of security concerns has been brought to the NRC administration on several occasions. At the Paducah Gaseous Diffusion plant there has been enforcement conferences and fines levied against USEC for poor attention to the security plans and liabilities to the security plan. When the USEC submitted their security plan to the NRC it was to authorize and posses Low Enriched Uranium (LEU) which is Category III material under NRC regulation. It is alarming that USEC was answering to a pre-decisional enforcement conference on June 5, 1998 to the apparent violation 98005-08 (Exceedance of possession limits of Highly enriched Uranium). To add on June 9, 1998 USEC places in the Open Line (an update of business activities at the Portsmouth Gaseous Diffusion Plant) Attachment #1; "The plant potentially exceeded HEU possession limits. (Note that this will likely result in no violation)".

The United Plant Guard Workers of America (UPGWA) Local 66 views this comment to be very serious in itself. The attitude of USEC having prior knowledge or feeling so comfortable to place in the Open Line to all employees "... Note

# United Plant Guard Workers of America (UPGWA)



Local 66

P.O. Box 1020, Piketon, Ohio 45661

---


that this will likely result in no violation", four days after the pre-decisional enforcement conference is simply appalling. The certification issue encompasses the physical protection of LEU of moderate and low strategic significance.

However, USEC has notified your agency (NRC) that the security sweeps of the X326 according to the presentation handout on the pre-decisional conference held on June 5, 1998 subtitled, "Planned Actions" to the apparent violation 98005-08, stated that the sweep "will provide a high degree of assurance that items containing uranium enriched above 10% has been identified". We feel this is not the case when you read and research the problem reports. We have attached Problem Reports for your review that should suggest to your agency that indeed the security sweeps are not being performed as an "excellent job". The procedure of the sweep paraphrased, is to utilize equipment ie. elephant gun, that identifies, characterizes the material and then the sweep personnel determines if the material is above the allowed amount of 10%. Next, is to place the material that is above the NRC limits of 10% and place the material in the DOE Material Storage Area (DMSA). The reason to have the questioning attitude about the integrity of the sweep, and the possibility of compromise, and the statement of USEC having a "high assurance" of no uranium enriched above 10% being left in the X326, is the problem reports and the concerns of the workers who actually worked the sweep jobs. It is so crucial, that your agency NRC needs to understand that the willingness to buy off on the security sweep project will give the employees and public the "false sense of security" that the sweep has been completed and that indeed a "high assurance" that HEU will not be in the facility, and be protected at the level of Category III instead at the level of Category I as it is today will have great implications and cost. Your agency (NRC) is buying off on a project that indeed is not going to give you the "high assurance" that USEC states you will have.

As the results and documentation of the following problem reports, it warrants the reason for NRC to also have the questioning attitude with language of "high assurance" being given at a pre-decisional conference.

Problem Reports are as follows: PTS-98-02857, PTS-9802355, PTS-98-03196, PTS-98-03277, PTS-98-03412, PTS-98-02384, PTS-98-02510, PTS-98-02442, PTS-98-02440, PTS-98-02420, PTS-98-01937. In the cases the HEU being found in the SWEPT area, was after the security police officers were moved due to the direction of

# United Plant Guard Workers of America (UPGWA)



**Local 66**

P.O. Box 1020, Piketon, Ohio 45661


---

management because the area had a "high assurance" of no uranium enriched above 10% being left in the area. If the sweep personnel and their highly technological equipment is so efficient to finding and identifying material to the level of "high assurance", then how do we explain the cases from the problem reports of all the HEU found in the SWEPT area after the sweep personnel declared the area free of HEU? Let it be noted that on July 31, 1998 the level of security at the X326 will be down graded to protect at the level of a Category III level. USEC will not be able to fall back on the statement that was used at the pre-decisional conference on June 5, 1998; "X326 building protected at DOE Category I level". Is this statement used at the pre-decisional conference one of "lassie-fair attitude"? If a mistake is made we have the Category I protection level to fall back on, this is not true after July 31, 1998.

We suggest that NRC take a long hard look at the problem reports submitted for your review and conduct interviews with personnel who actually worked and controlled the X326 sweep boundaries. NRC recertifying the Portsmouth Gaseous Diffusion Plant for low level might want to reconsider the approach with the X326 issue, and accepting the level of protection that USEC suggest, "High Assurance". The documented problem reports and the workers concerns should be considered very strongly before signing off on such an important project that has significant impact to the protection and safety of the employees and citizens in the area of the plant. Additionally, serious consideration needs to be given before recertification is approved, before the in depth investigations, interviews has been completed. The renewal of the certification of the Portsmouth Gaseous Diffusion plant located near Piketon, Ohio should be looked at due to questions, concerns, and apparent violations of exceedances of HEU possession limits. We feel very strongly that having exceedances of HEU in a NRC regulated area of Category III protection is serious and should not be taken lightly. How many apparent violations and problem reports of exceedances of HEU needs to be reported before NRC recommends that the contractor and or USEC increases the level of protection?

In conclusion, the recertification of the USEC areas without investigating, interviewing, and increasing the level of protection of the X326 building would be sending the wrong message to the employees, and public when addressing the goals of NRC of placing the safety and health as the importance. If HEU has been missed on several occasions, how much HEU has

# United Plant Guard Workers of America (UPGWA)




**Local 66**

P.O. Box 1020, Piketon, Ohio 45661

---

been missed that we have not found? If the HEU is missed after the protection limits are down graded, there is no second chance if the material falls into the wrong hands. NRC's recertification of the gaseous Diffusion Plant needs to have a questioning attitude toward the effort of USEC stating "high assurance".

Sincerely,

  
John K. Haberthy  
President UPGWA

cc: file



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D.C. 20555-0001

May 14, 1998

TO: All Persons Interested in Certification of Safe Operation of Gaseous Diffusion Enrichment Plants

SUBJECT: APPLICATION FOR RENEWAL OF CERTIFICATION OF GASEOUS DIFFUSION ENRICHMENT PLANTS

On April 15, 1998, the Nuclear Regulatory Commission received applications for renewal from the United States Enrichment Corporation to renew the Certificates of Compliance for the gaseous diffusion plants located in Paducah, Kentucky and Piketon, Ohio. Attached is the Federal Register notice acknowledging receipt of the renewal application and noticing the public comment period. Interested parties are invited to submit written comments on the application by June 19, 1998. There are no public meetings planned on the renewal applications.

If you have any questions, please contact the Special Projects Branch in Washington, D.C. at (301) 415-7192.

Sincerely,

A handwritten signature in black ink that appears to read "Robert C. Pierson".

Robert C. Pierson, Chief  
Special Projects Branch  
Division of Fuel Cycle Safety  
and Safeguards, NMSS

Enclosure: Federal Register Notice

Docket Nos. 70-7001, 70-7002  
GDP-1, GDP-2

cc: Interested Persons Lists

~~9805210099~~  
10ff

**NUCLEAR REGULATORY  
COMMISSION**

[Docket Nos. 70-7001, and 70-7002]

**United States Enrichment Corporation,  
Paducah and Portsmouth Gaseous  
Diffusion Plants, Notice of Receipt of  
Application for Certification Renewal  
For the Gaseous Diffusion Plants and  
Notice of Public Comment Period****I. Receipt of Application and  
Availability of Documents**

Notice is hereby given that the U. S. Nuclear Regulatory Commission (NRC or the Commission) has received by letters dated April 15, 1998, applications from the United States Enrichment Corporation (USEC) for the renewal of the certification of the gaseous diffusion plants (GDPs) located near Paducah, Kentucky and Piketon, Ohio. The NRC issued the initial certification for the GDPs on November 26, 1996 and assumed regulatory

oversight for the GDPs on March 3, 1997. The USEC renewal requests are for a five-year period. The USEC applications for renewal do not contain any changes to the existing documentation; previous applications, statements, and reports are incorporated by reference into the renewal application. The USEC application for the renewal of the Paducah Gaseous Diffusion Plant is based on USEC's previous Application, as revised through Revision 24 dated April 15, 1998, and USEC's previous Compliance Plan, as revised through Revision 7 dated March 20, 1998. No additional changes to the application or Compliance Plan are being requested. The USEC application for the renewal of the Portsmouth Gaseous Diffusion Plant is based on USEC's previous application, as revised through Revision 19 dated April 15, 1998, and USEC's previous Compliance Plan, as revised through Revision 6 dated March 12, 1998. No additional changes to the Application or Compliance Plan are being requested.

Copies of the renewal application for certification (except for classified and proprietary portions which are withheld in accordance with 10 CFR 2.790, "Availability of Public Records") are available for public inspection and copying at the Commission's Public Document Room (PDR) in the Gelman Building, 2120 L Street, NW, Washington, DC 20555 and in the Local Public Document Rooms (LPDRs) established for these facilities. A copy of the application for the Paducah plant is available at the Paducah Public Library, 555 Washington Street, Paducah, Kentucky 42003. A copy of the application for the Portsmouth plant is available at the Portsmouth Public Library, 1220 Gallia Street, Portsmouth, Ohio 45662. Copies of related correspondence and staff evaluations (except for portions withheld in accordance with 10 CFR 2.790) will also be made available at these public document rooms.

**II. Notice of Comment Period**

Any interested party may submit written comments on the renewal application for certification for either the Paducah plant or the Portsmouth plant for consideration by the staff. To be certain of consideration, comments must be received by June 19, 1998.

Comments received after the due date will be considered if it is practical to do so, but the Commission is able to assure consideration only for comments received on or before this date. Written comments on the application should be mailed to the Chief, Rules Review and

Directives Branch, Office of Administration, U.S. Nuclear Regulatory Commission, Washington, DC 20555, or may be hand delivered to 11545 Rockville Pike, Rockville, MD 20852 between 7:45 a.m. and 4:15 p.m. Federal workdays. Comments should be legible and reproducible, and include the name, affiliation (if any), and address of the commentor. All comments received by the Commission will be made available for public inspection at the Commission's Document Room located in Washington, DC and the Local Public Document Rooms located in Paducah, Kentucky and Portsmouth, Ohio. In accordance with 10 CFR 76.62 and 76.64, a member of the public must submit written comments to petition the Commission requesting review of the Director's decision on certification renewal.

**FOR FURTHER INFORMATION CONTACT:** Ms. Merri Horn, (301) 415-8126 or Mr. Yawar Faraz, (301) 415-8113; Office of Nuclear Material Safety and Safeguards, U.S. Nuclear Regulatory Commission, Washington, DC 20555.

Dated at Rockville, Maryland, this 28th day of April 1998.

For the Nuclear Regulatory Commission.  
*Carl J. Paperelli,*  
*Director, Office of Nuclear Material Safety  
and Safeguards.*

[FPR Doc. 98-11913 Filed 5-4-98; 8:45 am]

BILLING CODE: 7600-01-P

cc: Interested Persons Lists

Mr. Steve Folston  
General Manager  
Paducah Gaseous Diffusion Plant  
P.O. Box 1410  
Paducah, KY 42001

Mr. Larry Jackson  
Nuclear Regulatory Affairs Manager  
Paducah Gaseous Diffusion Plant  
P.O. Box 1410  
Paducah, KY 42001

The Honorable Paul Patton  
Governor, Commonwealth of Kentucky  
Capitol Building  
700 Capitol Avenue  
Frankfort, KY 40601

Mr. Crit Luallen, Deputy Secretary  
Governor's Executive Cabinet  
Capitol Building  
700 Capitol Avenue  
Frankfort, KY 40601

Dr. John A. Volpe, Ph.D., Manager  
Radiation Control Branch  
Cabinet for Human Resources  
Commonwealth of Kentucky  
275 East Main Street  
Frankfort, KY 40621-0001

Mr. James E. Bickford, Secretary  
Kentucky Cabinet for Natural Resources  
and Environmental Protection  
Capitol Plaza Tower, 5th Floor  
500 Mero Street  
Frankfort, KY 40601

Mr. Jack Wilson  
Environmental Response Supervisor  
Kentucky Cabinet for Natural Resources  
and Environmental Protection  
Capitol Plaza Tower  
500 Mero Street  
Frankfort, KY 40601

The Honorable Danny Cope  
McCracken County Commission  
400 Wilton Circle  
Paducah, KY 42300

The Honorable Buz Smith  
City Commissioner  
247 Old Orchard Road  
Paducah, KY 42001

The Honorable Dale Bradford  
McCracken County Commissioner  
5725 Bradford Road  
West Paducah, KY 42086

The Honorable Ned Buchanan  
McCracken County Commissioner  
1160 Highland Church Road  
Paducah, KY 42001

The Honorable Danny B. Orazine  
McCracken County Judge Executive  
McCracken County Courthouse  
Paducah, KY 42003-1797

Mr. Robert Qualls  
President  
Paducah Chamber of Commerce  
P.O. Box 810  
Paducah, KY 42002-0810

The Honorable Albert Jones  
Mayor of Paducah  
P.O. Box 2267  
Paducah, KY 42003

The Honorable Zana Renfro  
City Commissioner  
4805 Stanley Drive  
Paducah, KY 42001

The Honorable PJ Grumley  
City Commissioner  
4339 Miller  
Paducah, KY 42001

The Honorable Robert Coleman  
City Commissioner  
639 N 23rd Street  
Paducah, KY 42001

Mr. John Driskill, President  
United Plant Guard Workers of America  
Local 11  
Paducah Gaseous Diffusion Plant  
P.O. Box 1410  
Hobbs Road  
Paducah, KY 42002

Mr. David Fuller, President  
Paducah Local No. 3-550  
Oil, Chemical & Atomic Workers International Union  
2525 Cairo Road  
P.O. Box 494  
Paducah, KY 42001-0043

Mr. Gregg Bazzell  
DOE Safety Representative  
Paducah GDP  
P.O. Box 1410  
Paducah, KY 42001

Dr. Edward S. Ford, Chairman  
Central Midwest Interstate  
Low-Level Radioactive Waste Commission  
1035 Outer Park Drive  
Springfield, IL 62704

Reverend Velma M. Shearer  
124 Chestnut St., #210  
Englewood, OH 45322

Ms. Corinne Whitehead, President  
Coalition for Health Concern  
Route 9, Box 25  
Benton, KY 42025

Mr. Ronald Lamb  
10990 Ogden Landing Rd.  
Kevil, KY 42053

Mr. Craing Rhodes  
3883 Mt. Pleasant Rd.  
Brookport, IL 62910

Mr. Rick Cee  
Division Director  
OSHA Salt Lake Technical Center  
1781 South 300 West  
P.O. Box 65200  
Salt Lake City, UT 84165-0200

Mr. Felix M. Killar, Jr.  
Nuclear Energy Institute  
1776 I Street, NW  
Suite 400  
Washington, DC 20006-3708

Mr. Mark Donham  
RR#1  
Brookport, IL 62910

Ms. Kristi Hanson  
RR#1  
Brookport, IL 62910

Ms. Jotilley Dortch  
4205 Buckner Lane  
Paducah, KY 42001

Ms. Diana Salisbury  
Sycamore Environmental Awareness Group  
7019 Ashbridge Arnheim Road  
Sardinia, OH 45171

Mr. A. B. Puckett  
6365 Bethel Ch Road  
Kevil, KY 42053

Ms. Vina Colley  
3706 McDermott Pond Creek  
McDermott, OH 45652

Mr. Sherwood Bauman  
Save the Wills Creek Water  
Resources Committee  
6354 Cowgill Lane  
Cumberland, OH 43732

Ms. Susan L. Hiatt  
Director, OCRE  
8275 Munson Road  
Mentor, OH 44060-2406

## PORTSMOUTH

Mr. Lee Fink  
Portsmouth Site Director  
USEC Portsmouth Site Office  
P.O. Box 800  
Piketon, OH 45661

Mr. Morris Brown  
Plant Manager  
USEC Portsmouth Site Office  
P.O. Box 800  
Piketon, OH 45661

Mr. Gerry McGuire  
Nuclear Regulatory Affairs Manager  
USEC Portsmouth Site Office  
P.O. Box 800  
Piketon, OH 45661

Mr. James R. Williams  
Chief of Staff  
Ohio Emergency Management Agency  
2855 West Dublin-Granville Road  
Worthington, OH 43235-2206

Mr. Robert E. Owen, Chief  
Bureau of Radiological Health Sciences  
Ohio Department of Health  
35 East Chestnut Street  
P.O. Box 118  
Columbus, OH 43266-0588

Mr. Donald Schregardus, Director  
Environmental Protection Agency  
1800 Watermark Drive  
P.O. Box 1049  
Columbus, OH 43266-0109

The Honorable H. Cooper Snyder  
14th Ohio Senate District  
Ohio State House  
Broad and High Streets  
Columbus, OH 43216

The Honorable Doug White  
88th Ohio House District  
Ohio House of Representatives  
Ohio State House  
Columbus, OH 43216

The Honorable Vern Riffe III, Chairman  
Scioto County Commissioners  
Court House Room 104  
102 Seventh Street  
Portsmouth, Ohio 45662

The Honorable Wayne Bussler  
Scioto County Commissioner  
Court House Room 104  
102 Seventh Street  
Portsmouth, Ohio 45662

The Honorable John P. Knauff  
Scioto County Commissioner  
Court House Room 104  
102 Seventh Street  
Portsmouth, Ohio 45662

The Honorable Gregg Bauer  
Mayor of Portsmouth  
Municipal Building  
728 Second Street  
Portsmouth, Ohio 45662

Ms. Mary Moore, Director  
Portsmouth Chamber of Commerce  
P.O. Box 509  
Portsmouth, Ohio 45662

Ms. Kim Campbell  
Scioto County Local Emergency  
Planning Committee  
102 Seventh Street  
Portsmouth, Ohio 45662

Mr. Dan DeSantis  
President & CEO  
Southern Ohio Growth Partnership  
1020 7th Street, P.O. Box 509  
Portsmouth, Ohio 45662

Mr. Steve Carter  
Economic Development Director  
Ohio Valley Regional Development Commission  
740 Second Street  
Portsmouth, Ohio 45662

The Honorable Dean Lightle  
Mayor of Piketon  
City Building  
P.O. Box 562  
Piketon, Ohio 45661

Mr. Dave Jones  
Vice President, Operations  
Ohio Valley Electric Corp.  
P.O. Box 468  
Piketon, Ohio 45661

Mr. Tom Douglas, President  
UPGWA Local 66  
P.O. Box 628  
Piketon, Ohio 45661

The Honorable John Glenn  
U.S. Senate  
Room 503  
Hart Senate Office Building  
Washington, DC 20510

The Honorable R. Michael DeWine  
U.S. Senate  
Room 140  
Russell Senate Office Building  
Washington, DC 20510

The Honorable Ted Strickland  
U.S. House of Representatives  
Room 1107  
Longworth House Office Building  
Washington, DC 20515

Mr. George Vandemark, Director  
Ross County Emergency Management Agency  
P.O. Box 87  
Chillicothe, OH 45601

Mr. Roger Suppes, Chief  
Bureau of Radiation Protection  
Ohio Department of Health  
35 E. Chestnut, 7th Floor  
Columbus, OH 43266-0588

Mr. Thomas C. Douglas, President  
United Plant Guard Workers of American  
Amalgamated Local Union #66  
Piketon, OH 45661

Mr. Dan Minter, President  
Oil, Chemical, and Atomic Workers Union  
P.O. Box 467  
Piketon, OH 45661

**PROBLEM REPORT****- Use Black Ink and Print Only -****COPY**

Page 1 of 1

 PGDP HQ PORTSRichard CORIELL

Prepared by

58954

Badge Number

2212

Exemption

REPORT NUMBER

PR 1 PTS . 98 . 02357Organization No.: X-51 Group No.: 152 Mail Address: M5-1233Discovery Date: 9-6-98 Discovery Time: 0815 Building No.: X-326 Shift: ODrawing / Specification / Procedure No.: \_\_\_\_\_ Rev.: \_\_\_\_\_ In Hand Procedure?  Yes  No  N/A**DESCRIPTION OR NATURE OF PROBLEM:** (Attach additional sheets if needed)

WHILE PERFORMING HOLD-UP MEASUREMENTS IN THE X-326 BLDG. AT COLUMN R-34 ON THE OPERATING FLOOR CONTRACTORS FOUND (6) SIX ITEMS CONTAINING URANIUM ABOVE 10% ASSAY U-235. ITEMS AND ASSAYS ARE AS FOLLOWS ITEM #1, PEGTAIL AT 94.7% ENRICHMENT, ITEM #2, PEGTAIL AT 94.7% ENRICHMENT, ITEM #3 PEGTAIL AT 94.7% ENRICHMENT, ITEM #4 PEGTAIL AT 94.8% ENRICHMENT, ITEM #5 PEGTAIL AT 93.9% ENRICHMENT AND ITEM #6 STYLLET PIPE AT 81.8% ENRICHMENT.

**ACTIONS TAKEN:**

NOTIFIED BLDG. SUPERVISOR AND PERFORMED <sup>REC 9-6-98</sup> ~~PERFORMED~~ ENRICHMENT MEASUREMENTS.

Was the Problem Report reviewed with Manager?  Yes  No**ACTIONS RECOMMENDED:**

MATERIAL WILL BE QUANTIFIED ON TUESDAY APRIL 7, 1998 AND MATERIAL WILL BE STORED APPROPRIATELY STARTING WEDNESDAY APRIL 8, 1998. MATERIAL IN QUESTION IS PRESENTLY STORED WITHIN A MATERIAL ACCESS AREA.

Would you like to have a copy of this report when it is closed?  Yes  No**TO BE COMPLETED BY THE PBS***Salt Anf is NOT required**4-6-98*TYPE OF ESC:  OSR/TSR Q Item Safety System AQ Item NCS N/A

Justification/Comments/Actions:

- NO SECURITY ISSUE NOTED.
- REC. PR-PTS-98-02355 FOR NCS CONCERN FOR THIS ISSUE

**INITIAL ASSESSMENT**

Is Operability Decision Required?

<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Is Structure or Component Operable?

<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Is System Operable?

Reportable?

Categorization Date: 4-6-98Time: 1640*Eug R. Jaett*  
PBS Signature**TO BE COMPLETED BY COMMITMENT MANAGEMENT**

Xcode Condition Codes:

Performance Code:

Equipment Code:

Consequence Code:

UE-612  
(8-21-96)

# PROBLEM REPORT

- Use Black Ink and Print Only -

 PGDP     HQ     PORTS

DRAFT

Page 1 of 1

Prepared By	Badge Number	Extension	REPORT NUMBER
<u>TOM SEXTON</u>	<u>58046</u>	<u>6405</u>	<u>PR PTS - 98 02355</u>
Organization No.: <u>X12</u>	Group No.: <u>740</u>	Mail Address: <u>4002</u>	

Discovery Date: <u>4-6-98</u>	Discovery Time: <u>0945</u>	Building No.: <u>X-326</u>	Shift: <u>0</u>
Drawing / Specification / Procedure No.: _____		Rev.: _____	In Hand Procedure? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A

## DESCRIPTION OR NATURE OF PROBLEM: (Attach additional sheets if needed)

The Security Sweep Team Located Contaminated Metal parts with High U-235 count. Parts have been stored inside Deconior Material Safety Area, B.C. NCSA-Plant 062. All parts stored on small cart and wrapped in Plastic Bags. SEA

ACTIONS TAKEN: Stopped Security sweep Team, Security will not move any parts. Contracted X-3000 pss of possible NCS concern.  
\* NCS Engs directed all parts to be spaced & re-arrge to eff. Facility Plus spaced as per directed.

Was the Problem Report reviewed with Manager?  Yes  No

ACTIONS RECOMMENDED: To Continue Facility Clean-up by Follow All NCSA Requirements.

Would you like to have a copy of this report when it is closed?  Yes  No

## TO BE COMPLETED BY THE PSS

Safety Analysis NOT required

TYPE OF SSC:	<input type="checkbox"/> OSR/TSR <input type="checkbox"/> Safety System <input checked="" type="checkbox"/> NCS	<input type="checkbox"/> Q Item <input type="checkbox"/> AQ Item <input type="checkbox"/> N/A	Justification/Comments/Actions:  <ul style="list-style-type: none"> <li>• NCS responded And determined NCSA PLANT 062 Acc Regt. #5 violated - loss of one Control</li> <li>• 24 Hrue NRC Event</li> <li>• Spacing restored at 1130 hours</li> </ul>															
INITIAL ASSESSMENT	<table style="margin-left: auto; margin-right: auto;"> <tr> <td style="padding: 0 10px;">Y</td> <td style="padding: 0 10px;">N</td> <td style="padding: 0 10px;">N/A</td> </tr> <tr> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>			Y	N	N/A	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Y	N	N/A																
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>																
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>																
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>																
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>																
1. Operability Decision Required	<input type="checkbox"/>	<input checked="" type="checkbox"/>																
2. Is Structure or Component Operable?	<input type="checkbox"/>	<input type="checkbox"/>																
3. Is System Operable?	<input type="checkbox"/>	<input type="checkbox"/>																
4. Reportable?	<input type="checkbox"/>	<input checked="" type="checkbox"/>																
Categorization Date: <u>4/6/98</u>	Time: <u>2153</u>	<u>EDN</u> PSS Signature																

## TO BE COMPLETED BY COMMITMENT MANAGEMENT

Facilities Condition Code:	Performance Code:	Equipment Code:	Consequence Code:
----------------------------	-------------------	-----------------	-------------------

*Interagency* 17.1

COPY

## Checklist for Resolution/Recovery of NCS Anomalous Conditions

Problem Report #PR-PIS-98-02355 Facility X-326 Date 4/6/98 Time 0945

Brief Description of Problem: Several old tiger pigtail (formerly recall at PW) were found on a cart of potentially contaminated material. During + soon

Other potentially affected operations: Depending on NDA analysis may exceed material limit

Which NCSA(s) apply? NCSA - PLANT 062, A00 control #5 for 720%  
material

If no NCSA applies (or one cannot be determined within 4 hours) the Fissile Material Operation is considered to be unanalyzed. Shutdown the operation and submit event report. FMO is defined as an operation that could involve more than 15g  $^{235}\text{U}$  enriched to more than 1% assay. Ref. TSR J.11.2.

Is this a discrepancy in the description of the Fissile Material Operation in Part A of the NCSA? .....  Yes  No

If YES, does the discrepancy invalidate the evaluation of the FMO? .....  Yes  No

If YES, shutdown or limit the affected operation and revise the NCSA.

If NO, explain why the discrepancy does not affect the conclusions of the NCSA.

Comments: \_\_\_\_\_

Is this a potential violation of an NCSA requirement? .....  Yes  No

If YES, is the requirement an administrative aid or operator aid?

(If YES, this may not be a Reportable Event) .....  Yes  No

If NO, is the requirement a contingency control?

If YES, NCS Representative use the NCSA Part C Double Contingency Control Matrix (if present) to assist the PSS in determining whether a 4 hour or 24 hour reportable event exists.

Comments: Control #5, loss of spacing → 24-in edge-to-edge

Why are we safe right now? pig tails were < 5 inches in diameter → 5 in diameter is always safe

What actions do we need to take to restore compliance? Space pig tails 24in edge to edge

What do we need to do to ensure we remain in compliance and when will it be done? \_\_\_\_\_

NCS Representative John G. Rapp Badge 61266 Date 4/6/98 Time 1445

NCS Representative Ralph Lemmons Badge \_\_\_\_\_ Date \_\_\_\_\_ Time \_\_\_\_\_

FMO Rep. (Opt.) \_\_\_\_\_ Badge \_\_\_\_\_ Date \_\_\_\_\_ Time \_\_\_\_\_

PSS Tony R. Jaett Badge 58882 Date 4/6/98 Time 1550

### NEXT BUSINESS DAY REVIEW:

Response to this NCS anomalous condition is satisfactory. ....  Yes  No

If NO, write another PR and a Lessons Learned to document why the response was unsatisfactory and recommend a more appropriate response.

**PROBLEM REPORT**  
- Use Black Ink and Print Only -

Page 1 of \_\_\_\_\_

PGDP     HQ     PORTS

<u>Richard L. CORIELL</u>		<u>58954</u>	<u>2212</u>	REPORT NUMBER
Prepared By		Badge Number	Extension	
Organization No.: <u>X-51</u>	Group No.: <u>152</u>	Mall Address: <u>123 3</u>		<u>PR PTS - 98 - 03196</u>

Discovery Date: 1555-11-98 Discovery Time: 1550 Building No.: X-100 Shift: 0

Drawing / Specification / Procedure No.: \_\_\_\_\_ Rev.: \_\_\_\_\_ In Hand Procedure?  Yes  No  N/A

**DESCRIPTION OR NATURE OF PROBLEM:** (Attach additional sheets if needed)  
 WHILE PERFORMING HOLD-UP MEASUREMENTS IN THE X-326 CELL FLOOR  
 AT COLUMN A-63 A 55 GAL DRUM OF DAW HAD AN ENRICHMENT  
 OF 13.242% AND A VACUUM WITH A GP CONTAINER #009945  
 WITH AN ASSAY OF 17.891% ASSAY WAS LOCATED AT COLUMN #B-89.  
 BOTH CONTAINERS WILL HAVE QUANTITATIVE MEASUREMENTS STARTED  
 ON TUESDAY, MAY 12, 1998.

**ACTIONS TAKEN:** Contacted Bldg. Supervisor/FLM

Was the Problem Report reviewed with Manager?  Yes  No

**ACTIONS RECOMMENDED:**

Quantify assays to determine content. REMOVE GP CONTAINER from Vacuum GLENNER. Move to the APPROPRIATE STORAGE LOCATION PER PROCEDURE

Would you like to have a copy of this report when it is closed?  Yes  No

TO BE COMPLETED BY THE PBS Further Analysis and Follow-up, May 11, 1998

TYPE OF BSC:	<input type="checkbox"/> OSRTSR <input type="checkbox"/> Safety System <input checked="" type="checkbox"/> NCS	<input type="checkbox"/> Q Item <input type="checkbox"/> AQ Item <input type="checkbox"/> N/A	Justification/Comments/Actions:  <ul style="list-style-type: none"> <li>- Quantitative analysis being performed</li> <li>- 5/12/98</li> <li>- No possession limit concerns this time</li> <li>- NCS field representative investigated, no NCS issues identified, area compliance maintained</li> <li>- Security notified</li> </ul> <p><u>John Siler</u> PBS Signature</p>
INITIAL ASSESSMENT	Y <input type="checkbox"/> N <input type="checkbox"/> N/A <input checked="" type="checkbox"/>		
1. Operability Decision Required 2. Is Structure or Component Operable? 3. Is System Operable? 4. Reportable?	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Categorization Date: <u>5/11/98</u>	Time: <u>1859</u>		

TO BE COMPLETED BY COMMITMENT MANAGEMENT

Race Condition Code:	Performance Code:	Equipment Code:	Consequence Code:
----------------------	-------------------	-----------------	-------------------

UE-612  
(B-21-96)
**PROBLEM REPORT**  
**- Use Black Ink and Print Only -**
 PGDP     HQ PORTS**COPY**

Page 1 of \_\_\_\_\_

RICK CORIELI	58954	8212	REPORT NUMBER
Prepared By	Badge Number	Extension	PR PTS - 98 - 03277
Organization No.: X 51	Group No.: 152	Mail Address: 1233	

Discovery Date: 5-14-97 Discovery Time: 1715 Building No.: X-326 Shift: 0

Drawing / Specification / Procedure No.: Rev.: In Hand Procedure?  Yes  No  N/A

**DESCRIPTION OR NATURE OF PROBLEM:** (Attach additional sheets if needed)  
 AS PART of the X-326 CONFIRMATORY MEASUREMENT PROJECT THE FOLLOWING GP CONTAINERS WERE FOUND WHICH EXCEEDED 10% Q35. GP#006152, 13.5% ENRICHMENT, GP#009241, 12.6% ENRICHMENT, GP#009021 13.4% ENRICHMENT GP#05597, 13.05% ASSAY, GP#00843, 12.1% ASSAY, GP#00795, 13.1% ASSAY, GP#009036, 13.02% ASSAY, GP#009019, 14.3% ASSAY, GP#009631, 12.5% ASSAY, GP#008992, 12.77% ASSAY, GP#00923, 14.145% ASSAY, GP#008428, 13.4% ASSAY, GP#009553, 15.4% ASSAY, GP#008492, 9.971% ASSAY.

**ACTIONS TAKEN:**


ENRICHMENT MEASUREMENTS COMPLETED ON 5-14-97. ON 5-15-97 MATERIAL WILL BE MOVED TO THE NDA LAB TO PERFORM QUANTITATIVE MEASUREMENTS. CONTACTED BUILDING FLW. ALL MATERIAL IS CONTAINERIZED AND PROPERLY SPACED AT COLUMN B-B2

Was the Problem Report reviewed with Manager?  Yes  No**ACTIONS RECOMMENDED:**

UPON COMPLETION OF QUANTITATIVE MEASUREMENTS THE MATERIAL WILL BE PROPERLY DISPOSITIONED BY LOCATING IT IN THE X-326 L-CAGE.

Would you like to have a copy of this report when it is closed?  Yes  No

TO BE COMPLETED BY THE PGS SA REVIEW NO'S REQUIRED - UWS 5-14-98

TYPE OF SSC:	<input type="checkbox"/> OSR/TSR	<input type="checkbox"/> Q Item	Justification/Comments/Actions: STORED IN MA
	<input type="checkbox"/> Safety System	<input type="checkbox"/> AQ Item	NO SECURITY CONCERN
	<input type="checkbox"/> NCS	<input type="checkbox"/> N/A	NCS QUANTIFIED BY ANTS TO MOVE TO L CAGE
INITIAL ASSESSMENT	Y	N	N/A
1. Operability Decision Required	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
2. Is Structure or Component Operable?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
3. Is System Operable?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
4. Reportable?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Categorization Date:	5/14/98	Time:	1821
 <small>PGS Signature</small>			

TO BE COMPLETED BY COMMITMENT MANAGEMENT

Process Condition Code:

Performance Code:

Equipment Code:

Consequence Code:

UE-612  
(8-21-96)

# PROBLEM REPORT

- Use Black Ink and Print Only -

PGDP     HQ     PORTS

**COPY**

Page 1 of 1

<u>TERRY SENSE</u> Prepared By	1001048 Badge Number	3471 Extension	REPORT NUMBER
Organization No.: <u>25</u>	Group No.: <u>890</u>	Mall Address: <u>1212</u>	PR <u>PIS</u> . <u>98</u> . <u>0342</u>

Discovery Date: 5/20/98   Discovery Time: 10<sup>00</sup>   Building No.: X-3410   Shift: O

Drawing / Specification / Procedure No.: SAR TABLE I-3 C   Rev.: \_\_\_\_\_ In Hand Procedure?  Yes  No  N/A

**DESCRIPTION OR NATURE OF PROBLEM:** (Attach additional sheets if needed)

DOCUMENT E&I 98005-08 RECEIVED FROM NRC WHICH STATES PORTS POSSESSING MORE THAN 1000 GRAMS OF U<sup>235</sup> TO GREATER THAN 30% TS WEIGHT.

**ACTIONS TAKEN:**

P.R.-PIS-98-03357 WRITTEN ON 4/10/98 AFTER "SECURITY SWEEP" DISCOVERED MATERIAL ITEMS TRANSFERRED TO DOE REGULATED STORAGE AREA IN ACCORDANCE WITH PLANT POLICY.

Was the Problem Report reviewed with Manager?  Yes  No

**ACTIONS RECOMMENDED:**

ASSIGN TO D SHULER AS A REGULATOR/SCA FOR NRC ENFORCEMENT CONFINEMENT PREPARATIONS.

Would you like to have a copy of this report when it is closed?  Yes  No

**TO BE COMPLETED BY THE FSS**

<b>TYPE OF SSC:</b> <input type="checkbox"/> OSR/TSR <input type="checkbox"/> Q Item <input type="checkbox"/> Safety System <input type="checkbox"/> AQ Item <input type="checkbox"/> NCS <input checked="" type="checkbox"/> N/A	<b>INITIAL ASSESSMENT</b> <table style="margin-left: auto; margin-right: auto;"> <tr> <td style="width: 33.33%; text-align: center;">Y</td> <td style="width: 33.33%; text-align: center;">N</td> <td style="width: 33.33%; text-align: center;">N/A</td> </tr> <tr> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>	Y	N	N/A	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<i>Ronald Shuler</i> Justification/Comments/Actions: Compliance Plan issue NRA-98-SUBMITTED P.R.
Y	N	N/A															
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>															
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>															
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>															
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>															
1. Operability Decision Required 2. Is Structure or Component Operable? 3. Is System Operable? 4. Reportable?		<i>Ronald Shuler</i> <small>FSS Signature</small>															
Categorization Date: <u>5/20/98</u> Time: <u>1042</u>																	

**TO BE COMPLETED BY COMMITMENT MANAGEMENT**

Process Condition Code:	Performance Code:	Equipment Code:	Consequence Code:
Re D/210 (01-R30-NB2)-PORTS			

PROBLEM REPORT  
- Use Black Ink and Print Only -

COPY

Page 1 of \_\_\_\_\_

 PGDP     HQ     PORTS

BRENT McGINNIS Prepared By	59603 Badge Number	5758 Extension	REPORT NUMBER PR PTS - 98 - 02384
Organization No.: X-38	Group No.: 344	Mail Address: 2214	

Discovery Date: 4/7/98    Discovery Time: 13:10    Building No.: X-326    Shift: 0

Drawing / Specification / Procedure No.: N/A    Rev.: \_\_\_\_\_ In Hand Procedure?  Yes  No  N/A

**DESCRIPTION OR NATURE OF PROBLEM:** (Attach additional sheets if needed) The X-326 Sweep personnel have identified a trap on a piece of equipment located in USEC space that is greater than 10% (NDA measurements indicate  $35.2 \pm 2.8\%$  by wt  $^{235}\text{U}$  at 1 standard deviation). The item is located near column N33 on the operating floor.

**ACTIONS TAKEN:** Notified facility manager. We are in the process of performing quantitative NDA measurements on the item. Notified Nuclear Material Control & Accountability personnel.


Was the Problem Report reviewed with Manager?  Yes  No

**ACTIONS RECOMMENDED:** Once NDA measurements are completed the item should be moved to a DOE material storage area.

Would you like to have a copy of this report when it is closed?  Yes  No

## TO BE COMPLETED BY THE PSS

Safety Analysis N/T signed  
LBB-8  
4-7-98

TYPE OF SSC:	<input type="checkbox"/> OSR/TSR	<input type="checkbox"/> Q Item	Justification/Comments/Actions:  - NO APPARENT NCSA ISSUE - POTENTIAL COMPLIANCE PLAN ISSUE W/ EXCEEDING USEC/LMHS POSSESSION LIMITS OF MATERIAL ABOVE 20% ENRICHMENT - ANT TO PERFORM QUANTITATIVE NDA MEASUREMENTS WHICH WILL ALLOW DISPOSITION
Safety System	<input type="checkbox"/>	<input type="checkbox"/> AQ Item	
NCS	<input type="checkbox"/>	<input checked="" type="checkbox"/> N/A	
INITIAL ASSESSMENT	Y	N	N/A
1. Operability Decision Required	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Is Structure or Component Operable?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
3. Is System Operable?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
4. Reportable?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Categorization Date:	4/7/98		Time: 1846
 PSS Signature			

## TO BE COMPLETED BY COMMITMENT MANAGEMENT

Process Condition Code:

Performance Code:

Equipment Code:

Consequence Code:

UE-812  
(8-21-96)

# PROBLEM REPORT

- Use Black Ink and Print Only -

Page 1 of ..

3

 PGDP     HQ     PORTS

Rivind Capelli  
 Prepared By
58959

Badge Number

2212

Extension

REPORT NUMBER

PR PTS - 98 . 02510

Organization No.: X-51 Group No.: 152 Mail Address: MS-1283Discovery Date: 4-12-98Discovery Time: 1800Building No.: X-326Shift: ODrawing / Specification / Procedure No.: \_\_\_\_\_ Rev.: \_\_\_\_\_ In Hand Procedure?  Yes  No  N/A

## DESCRIPTION OR NATURE OF PROBLEM: (Attach additional sheets if needed)

WHILE PERFORMING HOLD-UP MEASUREMENTS IN THE X-326 FRICELTY AT COLUMN R-45, <sup>4-13-98</sup> V-39, AND V-40 ON THE OPERATING FLOOR (6) SIX ITEMS CONTAINING U-235 ABOVE 10% ASSAY WERE FOUND. THE ITEMS AND ASSAYS ARE AS FOLLOWS: ITEM 6, COLUMN R-45, ASSAY 88.222% (PRESSURE TRANSMITTER), ITEM B, COLUMN R-45, ASSAY 94.398% (PRESSURE TRANSMITTER), ITEM 14, COLUMN R-45 39.586% ASSAY (PRESSURE TRANSMITTER), ITEM A AT COLUMN V-39, ASSAY 82.854 (PRESSURE TRANSMITTER), ITEM B, COLUMN V-39 ASSAY 83.460% (PRESSURE TRANSMITTER), ITEM C, COLUMN V-40, ASSAY 44.620% (PRESSURE TRANSM.)

## ACTIONS TAKEN:

NOTIFIED BLDG. SUPERVISOR AND PERFORMED ENRICHMENT MEASUREMENTS.


Was the Problem Report reviewed with Manager?  Yes  No

## ACTIONS RECOMMENDED:

MATERIAL WILL BE QUANTIFIED ON TUESDAY APRIL 14, 1998 AND ONCE THE QUANTITY IS KNOWN THE MATERIAL WILL BE STORED PROPERLY.

Would you like to have a copy of this report when it is closed?  Yes  No

TO BE COMPLETED BY THE PSS SA REVIEW NOT REQUIRED UND 4-13-98

TYPE OF SSC:	<input type="checkbox"/> OSR/TSR	<input type="checkbox"/> Q Item	Justification/Comments/Actions:		
	<input type="checkbox"/> Safety System	<input type="checkbox"/> AQ Item	<ul style="list-style-type: none"> <li>- NO NCS ISSUED DUE TO NCS DEPT. MEETS PLANT 062 20%.</li> <li>- NO SECURITY <sup>ISSUED</sup> ITEM IS ALSO COLOCATED.</li> <li>- NMIC&amp;A MGR. ADVISED.</li> <li>- WAITING FOR MORE TO BE QUANTIFIED.</li> </ul>		
	<input type="checkbox"/> NCS	<input checked="" type="checkbox"/> N/A			
INITIAL ASSESSMENT	Y	N	N/A		
1. Operability Decision Required	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
2. Is Structure or Component Operable?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
3. Is System Operable?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
4. Reportable?	<input type="checkbox"/>	<input checked="" type="checkbox"/>			
Categorization Date:	<u>4/13/98</u>		Time:	<u>1742</u>	
 PSS Signature					

TO BE COMPLETED BY COMMITMENT MANAGEMENT

Process Condition Code:	Performance Code:	Equipment Code:	Consequence Code:
-------------------------	-------------------	-----------------	-------------------

UE-612  
(6-21-96)

COPY

# PROBLEM REPORT

- Use Black Ink and Print Only -

Page 1 of

 PGDP     HQ     PORTS

<u>RICK CORIEL</u> Prepared By	5A954 Badge Number	2012 Expansion	REPORT NUMBER <u>PR PTS - 98 - 62442</u>
Organization No.: <u>X-51</u>	Group No.: <u>1502</u>	Mail Address: <u>10233</u>	

Discovery Date: 4-9-98   Discovery Time: 1505   Building No.: X-326   Shift: O

Drawing / Specification / Procedure No.: \_\_\_\_\_ Rev.: \_\_\_\_\_ In Hand Procedure?  Yes  No  N/A

**DESCRIPTION OR NATURE OF PROBLEM:** (Attach additional sheets if needed)

While performing hold-up measurements in the X-326 Facility at Column G-25 on the operating floor, Contractors found three containers of uranium with enrichment above 10% assay U-235. Containers and assays are as follows: CONTAINER #1 GP009939, Assay 12.182%, CONTAINER #2 NO GP009938, Assay 12.413%, CONTAINER #3 NO. GP009925, ASSAY #16.830

**ACTIONS TAKEN:**

Notified Bldg. Supervisor and performed enrichment measurements  
Notified PSS Office


Was the Problem Report reviewed with Manager?  Yes  No

**ACTIONS RECOMMENDED:**

MEASURE for Quantification and disposition material appropriately.

Would you like to have a copy of this report when it is closed?  Yes  No

**TO BE COMPLETED BY THE PSS**

<b>TYPE OF SSC:</b> <input type="checkbox"/> OSR/TSR <input type="checkbox"/> Q Item <input type="checkbox"/> Safety System <input type="checkbox"/> AQ Item <input type="checkbox"/> NCS <input checked="" type="checkbox"/> N/A	<i>Safety Analysis NOT required</i> Justification/Comments/Actions: - NEED TO HAVE NMICLA CALCULATE POSSESSION LIMITS UNDER COMPLIANCE PLAN. <span style="float: right;">4-9-98</span>															
<b>INITIAL ASSESSMENT</b> <table style="margin-left: auto; margin-right: auto;"> <tr> <td style="text-align: center; width: 20px;">Y</td> <td style="text-align: center; width: 20px;">N</td> <td style="text-align: center; width: 20px;">N/A</td> </tr> <tr> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td></td> </tr> </table>		Y	N	N/A	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Y	N	N/A														
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>														
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>														
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>														
<input type="checkbox"/>	<input checked="" type="checkbox"/>															
1. Operability Decision Required <input type="checkbox"/> 2. Is Structure or Component Operable? <input type="checkbox"/> 3. Is System Operable? <input type="checkbox"/> 4. Reportable? <input type="checkbox"/>																
Categorization Date: <u>4/9/98</u> Time: <u>1928</u>																
 PSS Signature																

**TO BE COMPLETED BY COMMITMENT MANAGEMENT**

UE-612  
(8-21-98)

**PROBLEM REPORT**  
- Use Black Ink and Print Only -

PGDP     HQ     XPORTS

*COPY*

Page 1 of \_\_\_\_\_

LISA JENKINS

Prepared By

60E12

Badge Number

3601

Extension

REPORT NUMBER

Organization No.: X-38

Group No.: 300

Mail Address: 502C

PR PTS - 78 - 02440

Discovery Date: 4/9/98

Discovery Time: 1335

Building No.: X-326

Shift: O

Drawing / Specification / Procedure No.: UEZ-HP-RP1036 Rev.: 1 In Hand Procedure?  Yes  No  N/A

## DESCRIPTION OR NATURE OF PROBLEM: (Attach additional sheets if needed)

Pigtails found in clean area on floor on west side A/C. No radioactive material was found on pigtails. No boundary or posting of any kind around the pigtails.

ACTIONS TAKEN: Survey of pigtails and floor taken. No loose contamination was found. Enlarged nearby boundary to encompass pigtails.

Was the Problem Report reviewed with Manager?  Yes  No

## ACTIONS RECOMMENDED:

All radioactive material must be in proper locations until it is determined by conduct of radiological procedure.

Would you like to have a copy of this report when it is closed?  Yes  No

## TO BE COMPLETED BY THE PSS

Safety Analysis NOT required

*Kent*  
4-9-98

## TYPE OF JSC:

 CSR/TSR Q Item Safety System AQ Item NCS N/A

## Justification/Comments/Actions:

H-P and B ceiling issue for controlling RAA radioactive material.

## INITIAL ASSESSMENT

1. Operability Decision Required

Y	N	N/A
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

2. Is Structure or Component Operable?

3. Is System Operable?

4. Reportable?

Categorization Date: 4/9/98

Time: 1850

PSS Signature

## TO BE COMPLETED BY COMMITMENT MANAGEMENT

Process Condition Code:

Performance Code:

Equipment Code:

Consequence Code:

COPY

## Checklist for Resolution/Recovery of NCS Anomalous Conditions

Problem Report # \_\_\_\_\_ Facility X-320 Date 4/8/98 Time 1300

Brief Description of Problem: 3 SMALL DIAMETER CONTAINERS FOUND IN STORAGE AREA NEAR COLUMN G-24 WITH ENRICHMENT GREATER THAN 10% U-235

Other potentially affected operations: \_\_\_\_\_

Which NCSA(s) apply? PLANT 006, A03

If no NCSA applies (or one cannot be determined within 4 hours) the Fissile Material Operation is considered to be unclassified. Shutdown the operation and submit event report. FMO is defined as an operation that could involve more than 15g  $^{235}\text{U}$  enriched to more than 1% assay. Ref TSR 3.11.2.

Is this a discrepancy in the description of the Fissile Material Operation in Part A of the NCSA? .....  Yes  No

If YES, does the discrepancy invalidate the evaluation of the FMO? .....  Yes  No

If YES, shutdown or limit the affected operation and revise the NCSA.

If NO, explain why the discrepancy does not affect the conclusions of the NCSE.

Comments: \_\_\_\_\_

Is this a potential violation of an NCSA requirement? .....  Yes  No

If YES, is the requirement an administrative aid or operator aid?

(If YES, this may not be a Reportable Event) .....  Yes  No

If NO, is the requirement a contingency control? .....  Yes  No

If YES, NCS Representative use the NCSA Part C Double Contingency Control Matrix (if present) to assist the PSS in determining whether a 4 hour or 24 hour reportable event exists.

Comments: \_\_\_\_\_

Why are we safe right now? PLANT 006 COVERS THIS STORAGE AREA AND THOSE TYPES OF CONTAINERS. CONTENTS OF CONTAINERS NOT REQUIREMENTS OF PLANT 006 AND ITEMS STORED ARE STORED PER PLANT 006 REQUIREMENTS. THERE IS NO NCS VIOLATION.

What actions do we need to take to restore compliance? \_\_\_\_\_

What do we need to do to ensure we remain in compliance and when will it be done? \_\_\_\_\_

NCS Representative RE Lammie Badge 58296 Date 4/8/98 Time 2211  
NCS Representative Dm D'Amico Badge 59339 Date 4/8/98 Time 2219  
FMO Rep. (Opp.) RE Lammie Badge \_\_\_\_\_ Date \_\_\_\_\_ Time \_\_\_\_\_  
PSS RE Lammie Badge 55676 Date 4/8/98 Time 2330

### NEXT BUSINESS DAY REVIEW:

Response to this NCS anomalous condition is satisfactory. .....  Yes  No

If NO, write another PR and a Lessons Learned in Annexure section.

UE-612  
(8-21-96)**PROBLEM REPORT**  
- Use Black Ink and Print Only -

Page 1 of \_\_\_\_\_

 PGDP     HQ     PORTS

<u>Richard L. CORIELL</u> Prepared By	<u>58954</u> Badge Number	<u>2212</u> Extension	REPORT NUMBER
Organization No.: <u>X-51</u>	Group No.: <u>152</u>	Mail Address: <u>445-1233</u>	<u>PR PTS - 98 - 02420</u>

Discovery Date: 4-8-98 Discovery Time: 1300 Building No.: X-326 Shift 0Drawing / Specification / Procedure No.: \_\_\_\_\_ Rev.: \_\_\_\_\_ In Hand Procedure?  Yes  No  N/A**DESCRIPTION OR NATURE OF PROBLEM:** (Attach additional sheets if needed)

WHILE PERFORMING HOLD-UP MEASUREMENTS IN THE X-326 FACILITY AT COLUMN G-24 ON THE OPERATING FLOOR, CONTRACTORS FOUND THREE CONTAINERS OF URANIUM WITH ENRICHMENT ABOVE 10% ASSAY U-235. CONTAINERS AND ASSAYS ARE AS FOLLOWS: CONTAINER #557180, POLY BOTTLE WITH ENRICHMENT OF 14.6% ASSAY, ITEM #2 GP CONTAINER #GP009507 WITH ENRICHMENT OF 36.53% ASSAY AND ITEM #3 CONTAINER # GP005327 WITH ENRICHMENT OF 84.74% ASSAY.


**ACTIONS TAKEN:**

NOTIFIED BLDG. SUPERVISOR AND PERFORMED ENRICHMENT MEASUREMENTS.  
NOTIFIED PSS OFFICE.

Was the Problem Report reviewed with Manager?  Yes  No**ACTIONS RECOMMENDED:**

MEASURE FOR QUANTIFICATION AND DISPOSITION MATERIAL APPROPRIATELY

Would you like to have a copy of this report when it is closed?  Yes  No**TO BE COMPLETED BY THE PSS** *Sample Analysis is NOT required*

TYPE OF SSC:	<input type="checkbox"/> OSR/TSR	<input type="checkbox"/> Q Item	Justification/Comments/Actions: <i>I. Roberts 4-8-98</i>
	<input type="checkbox"/> Safety System	<input type="checkbox"/> AQ Item	- PLANT 006 COVERS THIS STORAGE AREA. RL 4/8/4
	<input checked="" type="checkbox"/> NCS	<input type="checkbox"/> N/A	- NO NCS VIOLATION
INITIAL ASSESSMENT	Y	N	
1. Operability Decision Required	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
2. Is Structure or Component Operable?	<input type="checkbox"/>	<input type="checkbox"/>	
3. Is System Operable?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
4. Reportable?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Categorization Date:	<u>4/8/98</u>		Time: <u>2339</u>
 <i>Greg Quigley</i> PSS Signature			

**TO BE COMPLETED BY COMMITMENT MANAGEMENT**

Process Condition Code:

Performance Code:

Equipment Code:

Consequence Code:

PROBLEM REPORT  
- Use Black Ink and Print Only -

COPY

Page 1 of \_\_\_\_\_

 PGDP     HQ     PORTS

RICK CORIEL

Prepared By

58954

Badge Number

2212

Extension

REPORT NUMBER

PR 1PTS - 98 01937

Organization No.: X-51 Group No.: 152 Mail Address: 1233

Discovery Date: 3-20-98

Discovery Time: 1610

Building No.: X-326

Shift 0

Drawing / Specification / Procedure No.: Rev.: In Hand Procedure?  Yes  No  N/A

## DESCRIPTION OR NATURE OF PROBLEM: (Attach additional sheets if needed)

WHILE PERFORMING HOLD-UP MEASUREMENTS IN THE X-326 BLDGNG AT COLUMN 100 ON ALWAYS-SAFE VACUUM CLEANERS AND CONTRACTOR PERSONNEL DISCOVERED VACUUMS # SV-003 AND # SV-002 TO CONTAIN U-235 ABOVE 10% ASSAY IN THE ROUGHING FILTERS. CART # SV003 AND ANTSTICKER # 013812 HAS AN ASSAY OF 15.678% U-235 AND CART # SV-002 AND ANTSTICKER # 013813 HAS AN ASSAY OF 18.619% U-235.

## ACTIONS TAKEN:

PLACED SERIAL # 18003 AND 18004 ON THE ROUGHING FILTER OF CART # SV-002, SERIAL # 18002 AND # 18001 PLACED ON ROUGHING FILTER OF CART # SV-003.

Was the Problem Report reviewed with Manager?  Yes  No


ACTIONS RECOMMENDED:  
 FILTERS WILL BE QUANTIFIED BY WEDNESDAY MARCH 25, 1998 AND FILTERS WILL BE STORED APPROPRIATELY ON THURSDAY MARCH 26, 1998 ONCE THE QUANTITY IS KNOWN. FILTERS ARE STORED WITHIN A MATERIAL ACCESS AREA.

Would you like to have a copy of this report when it is closed?  Yes  No

## TO BE COMPLETED BY THE PES

Safety Analysis NOT required

3-21-98

TYPE OF SSC:	<input type="checkbox"/> OSR/TSR	<input type="checkbox"/> Q Item	Justification/Comments/Actions:
	<input type="checkbox"/> Safety System	<input type="checkbox"/> AQ Item	<ul style="list-style-type: none"> <li>• AQ-NCS ITEM</li> <li>• ASSAY WITHIN ALLOWABLE LIMITS FOR LAMS POSSESSION</li> <li>• ASSAY WITHIN ALLOWABLE NCSA REQUIREMENTS</li> </ul>
	<input type="checkbox"/> NCS	<input checked="" type="checkbox"/> N/A	
INITIAL ASSESSMENT	Y	N	N/A
1. Operability Decision Required	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Is Structure or Component Operable?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Is System Operable?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Reportable?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Categorization Date:	3/20/98	Time:	2341
 PES Signature			

## TO BE COMPLETED BY COMMITMENT MANAGEMENT

Radiation Condition Code:	Performance Code:	Equipment Code:	Consequence Code:
---------------------------	-------------------	-----------------	-------------------

Final



UNITED STATES ENRICHMENT CORPORATION  
PORTSMOUTH GASEOUS DIFFUSION PLANT  
PRE-DECISIONAL ENFORCEMENT CONFERENCE

June 5, 1998

## AGENDA

- A. Introduction J. Miller
  - B. Apparent Violations 98005-01 and 98005-02  
(Control of Plant Components that contain Uranium Deposits  
Greater than Safe Mass) S. Fout
  - C. Apparent Violations 98005-04 thru 98005-06  
(Operation of an Autoclave  
with a Safety Valve Actuator Improperly Installed) P. Müsser
  - D. Apparent Violation 98005-07  
(Maintenance and Surveillance Activities Associated with  
Air Operated Safety Valves on the Autoclaves) M. Hasty
  - E. Apparent Violation 98005-08  
(Exceedance of Possession Limits) D. Shisler
  - F. Concluding Remarks M. Brown
- Appendix (Summary of Test Results of Air Operated Valves)



Control of Plant Components that Contain  
Uranium Deposits Greater than Safe Mass

## BACKGROUND

- TSRs 2.2.3.15/2.7.3.14 contain conditions for PEH deposits:
  - Condition A requires deposits be maintained in a fluorinating environment.
  - Condition B requires that deposits not in a fluorinating environment be pressured to  $\geq 14$  psia within 8 hours of identification.
- Fluorinating environment:
  - Presence of a measurable concentration of  $\text{UF}_6$ ,  $\text{ClF}_3$ , or  $\text{F}_2$ .
  - Determined by a  $\text{UF}_6$  concentration  $> 20$  ppm at 1 psia or  $> 1$  ppm at atmosphere.

**CELL 29-3-6**

- USEC has determined that a fluorinating environment was maintained for this cell. Therefore, a TSR violation did not occur. This event did reveal weaknesses in our cell sampling program.

Chronology of Events		
Date	Time	Description
5/5	0915	2 samples taken (1 from stage 1, and 1 from stage 2) at the Local Control Center (LCC)
5/5	1115	Sample results obtained, both samples showed that a fluorinating environment existed. - Stage 1 had low UF <sub>6</sub> concentration (22.31 ppm). - Stage 2 had high UF <sub>6</sub> concentration (1412.4 ppm).
		(Note: the IR incorrectly states that the sample from stage 1 showed that a fluorinating environment did not exist.)
5/5	1230 and 1404	Resamples were taken from Stages 1 and 3 at the LCC, respectively.
5/5	1630	Sample results obtained - Stage 1 showed that a fluorinating environment does not exist (10.53 ppm). - Stage 3 showed that a fluorinating environment exists (2630.1 ppm).  • First Line Manager discusses the sample results with the Building Manager. These individuals determined that a fluorinating environment existed and that there was an anomaly with the stage 1 sample results.

**CELL 29-3-6 (cont'd)**

Chronology of Events		
Date	Time	Description
5/6	~0700 to noon	Building Manager initiates investigation of sample results from Stage 1 to determine if there is wet air inleakage • FLM walks down sample lines; no evidence of wet air inleakage observed.
5/6	1444 and 1644	Samples were taken again for stage 1 and 3, respectively. Samples were taken at the blowout preventer (BOP) nearest to the compressor and the deposit.
5/6	1535 and 1800	Sample results obtained. The samples from both stages showed that a fluorinating environment did not exist.
5/6	~1800	TSR action statement is entered and cell is pressurized.

- Further investigation has determined that samples taken from stages 1 and 3 at the BOP were not representative since the cell was in a static condition (i.e., the compressor was shutdown).
- On June 1, 1998, the cell sampling procedure was revised to address sampling shutdown cells at BOP

## **CELL 29-5-2**

### **Background**

- On April 7, 1998, samples taken from this cell showed it was in a fluorinating environment but had low UF<sub>6</sub> concentration.
- Resamples taken on April 8, 1998.
  - Fluorinating environment did not exist for this cell.
  - Cell was pressurized in accordance with the TSR.
- During further review of the cell conditions, the Cascade Controller identified that the previous week's samples had not been recorded.
- Cascade Controller requested and received the March 31, 1998, sample results.
  - Sample results also indicated that a fluorinating environment did not exist for this cell.
  - Results of the samples were not processed and communicated to Operations in a timely manner (i.e., 8 days vice hours).
  - Operations personnel failed to follow-up with the laboratory as to the results of the sample.

**CELL 29-5-2 (cont'd)**

**Root Causes**

1. Lack of a procedure for verifying fluorinating environment for PEH deposits.
2. Compensatory actions implemented on January 30, 1998, did not contain sufficient rigor:
  - a. No requirements to submit written requests for samples;
  - b. No requirements to provide written sample results;
  - c. Did not address timeliness of communicating sample results;
  - d. Did not address actions to take for anomalous sample results.

## CELL 29-5-2 (cont'd)

### Immediate Corrective Actions

- DOIs revised on April 20, 1998 to include additional controls: (Root Cause #2)
  - Requirements to submit written requests for lab samples weekly.
  - Requirements to notify the lab of specific reporting constraints.
  - Requirements for lab personnel to provide written sample results within 4 hours from obtaining samples.
  - Requirements to record and trend the data and identify if an adverse condition is developing so prompt mitigating actions can be initiated prior to exceeding authorized safety limits.
- Training was conducted for Laboratory and Cascade Control personnel on communication of sample results

### Additional Corrective Actions

- Issued a PEH tracking procedure on May 11, 1998 which superseded the DOIs. (Root Cause #1)
- Actions to address anomalous sampling results.
- An "extent of condition" review will be completed by October 2, 1998, to determine if there are other TSR requirements that require additional procedural coverage.

## CELL 29-5-2 (cont'd)

### Mitigating Factors

- There was no possibility of an unplanned criticality in cell 29-5-2 :
  - Cell 29-5-2 was taken off-stream in July 1997 due to plugging. The cell was evacuated but not purged to a UF<sub>6</sub> negative. From February 4, 1998, to March 24, 1998, the cell showed positive results for UF<sub>6</sub> and maintained a constant pressure of 6.5 psia.
  - If cell 29-5-2 had wet air inleakage, at plant temperature and moisture conditions, it would take 2.7 years to accumulate enough moisture to achieve optimum moderation of this size deposit at 5.5% enrichment.
  - The size of this deposit is less than the minimum critical mass of a UO<sub>2</sub>F<sub>2</sub> deposit at an enrichment of 5.5%, with optimum geometry and full reflection.
- This event was self-identified and reported to NRC in accordance with Bulletin 91-01.
- USEC does not believe that escalated enforcement action is warranted.
  - Issue is of low safety significance.
  - Only one example of failure to meet TSR.

## Operation of an Autoclave with a Safety Valve

### Actuator Improperly Installed

## BACKGROUND

- 3/24/98 - Actuator for Autoclave Containment Isolation Valve FV-416X replaced.
- Work was to be performed in accordance with procedure XP4-TE-MM4104.
- This procedure was revised on December 13, 1996, to provide detailed guidance to assure proper actuator installation.
- The Maintenance Mechanic performing replacement did not follow procedure. As a result, the actuator was installed incorrectly.
- The mechanic believed that "General Intent" procedures did not need to be followed verbatim.
- Procedure UE2-PS-PS1034 states that "General Intent" procedures are to be followed as written.
- An operational check was not performed as required by XP4-TE-MM4104.

## **BACKGROUND (cont'd)**

- 3/25/98      The operator performing the Post Maintenance Test (PMT) failed to recognize the improper valve position indication and signed off the test as satisfactorily completed.
- 3/25-27/98     Two cylinders are fed from the autoclave.
- 3/27/98      While performing a conductivity cell test, an operator discovers that FV-416X is operating opposite its design function.

## **ROOT CAUSES**

1. Failure to follow procedure due to a lack of understanding regarding compliance with "General Intent" procedures.
2. Lack of procedure guidance for developing and performing PMTs.

### **Contributing Causes:**

1. When the criteria for an "In-Hand" procedure was revised in August 1997, a review was not performed to determine if existing "General Intent" procedures should be recategorized.
2. The training module concerning use of procedures was inconsistent with UE2-PS-PS1034, "Use of Procedures" regarding compliance with "General Intent" procedures.
3. Procedure XP4-TE-MM4104 does not provide specific guidance as to what an "operational check" involves.
4. Poor communication between operators during the performance of the PMT.

## CORRECTIVE ACTIONS

### Immediate Corrective Actions

- On March 27, 1998, valve actuator was removed, reoriented to its correct position, and a satisfactory PMT (including a leak rate test) was performed.
- Valve actuators on the other autoclaves were verified to be in the proper orientation.
- Other actuators that are known to have been replaced were inspected to determine compliance with procedure XP4-TE-MM4104.
- Briefings were conducted with Operations and Maintenance personnel on the "Lessons Learned" from this event. (RC #1)
- Maintenance personnel were instructed to treat "General Intent" procedures similar to "In-Hand" (this is a temporary measure pending a more in-depth review to determine proper categorization). (RC#1)
- The procedure requirements for proper installation of valve actuators have been reviewed with maintenance personnel in the X-340 complex. (RC#1)

## CORRECTIVE ACTIONS (cont'd)

### Immediate Corrective Actions (cont'd)

- The PMT requirements for replacement of actuators have been revised to include leak rate testing per the Technical Safety Requirements. (RC#2)
- Peer reviews of PMTs were instituted by Engineering to ensure that TSR surveillances and the requirements of the Quality Assurance Plan (QAP) are met for TSR related structures, systems, and components. (RC#2)
- The training module on the use of "General Intent" procedures has been revised. (CC#2)

### Additional Corrective Actions

- Conduct site meetings by June 19, 1998, to emphasize the importance of procedural adherence. (RC#1)
- Revise procedure XP4-TE-MM4104 by July 1, 1998, to enhance the criteria for ensuring correct actuator installation. (CC#3)

## **CORRECTIVE ACTIONS (cont'd)**

### **Additional Corrective Actions (cont'd)**

- Revise the affected autoclave startup procedures by August 14, 1998, to include steps for checking applicable containment valve position.
- Review and develop a schedule to revise those "General Intent" procedures which should be reclassified as "In Hand," by September 30, 1998. (CC#1)
- Review and, as necessary, revise the PMT requirements by June 19, 1998, for autoclave work packages. (RC#2)
- Re-emphasize management expectations on Conduct of Operations by July 31, 1998, with Operations personnel. (CC#4)
- The PORTS Safety and Safeguards Quality (SS&Q) organization performed an assessment of the PORTS PMT program. Recommendations were made to improve the PORTS PMT program.
- Issue proceduralized guidance by July 14, 1998, on developing PMTs which will address: (RC#2)
  - Applicable TSR surveillance tests;
  - QAP requirements;
  - The SS&Q audit recommendations.

## **MITIGATING FACTORS**

- During the time that the autoclave was in operation with isolation valve FV-416X inoperable, there was a redundant manually operated valve (HV-386-4) that was closed and verified to be operable. Thus, this event was of low safety significance.
- Prompt and thorough corrective actions were initiated by USEC upon discovery of this event.

## Maintenance and Surveillance Activities

## Associated with Air Operated Safety Valves on the Autoclaves

## **BACKGROUND**

- On April 9, 1998, in response to a concern raised by the NRC Resident Inspector regarding the adequacy of containment valve surveillance testing, a functional check was performed on several autoclaves in the X-342 and X-343 facilities.
- The functional check involved valving off plant air and verifying that air operated containment valves still closed while simulating autoclave containment.
- Several containment valves failed to close as designed when the normal plant air supply was valved off.
- Other autoclave isolation valves with air-to-close actuators were subsequently tested (see Appendix).
- As of June 1, 1998:
  - 10 of the 13 autoclaves have been tested;
  - 55 of 73 total valves tested;
  - 15 valves failed testing criteria, but would still close on loss of air;
  - 9 valves failed to close on loss of air.

### **BACKGROUND (cont'd)**

- The air-to-close valves in systems at ERP, LAW, Tails, and X-705 have been tested and found to operate as designed (11 valves).
- In January 1996, a similar issue was identified with the Parent Cylinder Safety Valves (PCSVs).
- Corrective actions for this previous event were narrowly focused on the PSCVs and were not extended to include other air-to-close valves.

## **ROOT CAUSE**

- Failure to develop a testing program to demonstrate that autoclave air-to-close valves will perform their design function on a loss of normal supply air.

## **CORRECTIVE ACTIONS**

### Immediate Corrective Actions

- Affected autoclaves were declared inoperable.
- All safety-related systems with air-to-close valves were either declared inoperable (i.e., X-705 calciner) or an Operability Evaluation was performed (i.e., ERP, LAW, and Tails).
- Test criteria was established, the valves were tested and repaired as necessary, and the autoclaves returned to service.

## CORRECTIVE ACTIONS (cont'd)

### Additional Corrective Actions

- Issue formal testing criteria by June 17, 1998, for surveillance testing of the backup air reservoir tanks. Testing will be conducted via work packages. (RC)
- Testing of backup air reservoirs will be scheduled to be performed on a quarterly basis. This testing will be initiated on June 28, 1998.
- Revise the affected procedures by September 30, 1998, to include testing of the backup air reservoirs. (RC)
- An action plan will be developed by July 10, 1998, that verifies SAR design bases systems credited for backup are being properly tested. (RC)

## MITIGATING FACTORS

- No impact on safety:
  - With normal plant air available, the containment system would have closed the valves.
  - With a loss of plant air, the autoclave automatically shuts down and containment is not required.
- No credit taken in TSR bases statements for closure of valves on loss of normal air.
- No design basis accident which takes credit for loss of air concurrent with a cylinder rupture in an autoclave.
- Prompt and thorough corrective actions were initiated by USEC upon discovery of this event.
- USEC does not believe that escalated enforcement action is warranted for this violation.

## Exceedance of Possession Limits

## BACKGROUND

### Highly Enriched Uranium (HEU) Suspension Activities (1992-1996)

- DOE program designed to remove as much HEU as practical from X-326.
- Included installed and uninstalled process equipment.
  - Cell treatment of installed equipment.
  - Over 650 individual components processed (compressors, convertors, coolers, pumps, traps, etc.).
- Included containerized nuclear materials (e.g., cylinders, polybottles, cans, drums).
- Suspension activities completed on September 26, 1996.

## **BACKGROUND (cont.)**

### **Compliance Plan (CP) Issue A.4 Actions**

- Required USEC to certify that materials remaining in X-326 following HEU Suspension would not exceed NRC Category III.
- CP required USEC to perform a static inventory of nuclear materials - completed.
- USEC letter to NRC, October 31, 1996, provided certification required by CP Issue A.4.
- Certification based on inventory records;
- Certification excluded:  
"Any other nuclear materials which may be discovered to be present in these areas as a result of legacy DOE operations, but which are not included on official nuclear material accounting records as described in Section 3.7 of the SAR."

## **BACKGROUND (cont.)**

### **DOE X-326 Physical Security Sweep**

- DOE program required prior to downgrading security in X-326.
- Comprehensive Non-Destructive Assay (NDA) scans of areas in X-326 were performed for DOE to identify any unknown HEU-bearing items.
- DOE approved Security Plan includes actions to be taken upon discovery of HEU materials.
- Sweep activities initiated October 1997.
- Sweep has found DOE HEU material which has been moved to a DOE Material Storage Area (DMSA).
- On April 6, 1998, 6 additional items discovered that contained a total of about 775g U-235 as HEU.

## USEC ACTIONS

- Quantified HEU present in identified items.
- Material promptly transported to DOE's DMSA using approved procedures.
- Notified NRC Resident Inspector.
- X-326 Building protected at DOE Category I level.

JOINT STATEMENT OF UNDERSTANDING  
BETWEEN NRC AND DOE  
DECEMBER 20, 1993

"During the entire period that uranium enriched to 20 percent or more U<sup>235</sup> is located at the Portsmouth facility, DOE will retain title to and possess such uranium and will be solely responsible for providing for, establishing and maintaining nuclear safety, safeguards and security controls applicable to such uranium."<sup>11</sup>

## CONCLUSIONS

- No safety and safeguards significance.
- All applicable procedures and requirements were met.
- USEC believes no violation of possession limits occurred.
- CP Issue A.4 does not clearly describe:
  - Limitations of HEU suspension activities.
  - Plans to conduct X-326 security sweep.
  - Actions to be taken upon discovery of HEU materials other than residual deposits.

## **PLANNED ACTIONS**

- Complete security sweep of X-326 Building by September 30, 1998, to provide high degree of assurance that items containing uranium enriched above 10% have been identified.
- Promptly move any identified items to DMSAs in accordance with approved procedures.

**APPENDIX**

**TEST RESULTS OF AIR-TO-CLOSE  
OPERATED VALVES**

## AIR-TO-CLOSE AS-FOUND TESTING DATA

**X-342A**

Valve Tested	Valve #	Test	X342-1	X-342-2
Blowdown	FV-_10X	loss of air low air	Failed Passed	To be tested To be tested
Conductivity A	FV-_11X1	loss of air low air	Passed Passed	To be tested To be tested
Conductivity B	FV-_11X2	loss of air low air	Passed Failed	To be tested To be tested
PCSV	FV-_04	low air	Failed	To be tested
Shell Vent	FV-_16X	low air	Passed	To be tested

**X-343**

Valve Tested	Valve #	Test	X-343-1	X-343-2	X-343-3	X-343-4	X-343-5	X-343-6	X-343-7
Blowdown	FV-_10X	loss of air low air	Failed Not tested	Failed Passed	Valve closed ** Valve closed **	Failed Passed	Passed Passed	Passed Passed	To be tested To be tested
Conductivity A	FV-_11X1	loss of air low air	Passed Passed	Passed Passed	Valve closed ** Valve closed **	Passed Passed	Passed Passed	Failed Failed	To be tested
Conductivity B	FV-_11X2	loss of air low air	Passed Failed	Passed Passed	Valve closed ** Valve closed **	Passed Passed	Passed Passed	Passed Passed	To be tested To be tested
PCSV	FV-_04	low air	Passed	Passed	Passed	Passed	Passed	Passed	To be tested
Shell Vent	FV-_16X	low air	Failed	Failed	Failed	Passed	Failed	Failed	To be tested

**X-344**

Valve Tested	Test	X-344-1		344-2		X-344-3		X-344-4	
		CV-125	CV-155	CV-155	To be tested To be tested	FV-185	Failed Failed	FV-235	To be tested
Blowdown Exhaust	loss of air low air	FSV-122	Failed Passed	FSV-152	To be tested To be tested	FSV-182	Passed Passed	FSV-232	Passed Failed
Blowdown Exhaust	loss of air low air	FSV-122X	Failed Passed	FSV-152X	To be tested To be tested	FSV-182X	Passed Passed	FSV-232X	Passed Failed
Condensate Drain	loss of air low air	PSV-106X	Passed Passed	PSV-136X	To be tested To be tested	FSV-166	Passed Passed	FSV-216	Passed Failed
Condensate Drain	loss of air low air	None	N/A	None	N/A	FSV-166X	Passed Passed	FSV-216X	Passed Failed
Vacuum Relief	loss of air low air	PCV-112X	Failed Failed	PCV-142X	To be tested To be tested	FSV-196	Passed Passed	FSV-246	Passed Failed
PCSV	low air	FV-115	Passed	FV-155	To be tested	FSV-191	Passed	FV-241	Failed
Shell Vent	low air	PCV-114X	Failed	PCV-144X	To be tested	None	N/A	None	N/A

**Summary of As-Found Testing (6/1/98)**

	X-342A	X-343	X-344A	Total
Valves Tested to Date	5	36	20	66
Successes***	2	20	9	31
Failures**	3	10	11	24
Total ATC Valves	10	36	28	73

\*\* As-Found closure time not documented initially. Remaining valves document As-Found closure times and Re-Test data documented in package.

\*\*\* Any valve testing either the "loss of air" or "low air" testing was classified as a Failure. Any valve not classified as a failure was considered a success.

Passed = Valve closes in less than 10 seconds.

Failed = Valve fails to close in less than 10 seconds, unless otherwise noted.

# The Open Line

An update of business activities at the Portsmouth Gaseous Diffusion Plant



**Our Vision:** To be recognized as the production team that makes USEC the number one worldwide supplier of reliable, high quality, and low cost uranium enrichment services.

Tuesday, June 9, 1998

Stories for *The Open Line* should be mailed to MS 1225.

## Straight Talk by Morris Brown

On Friday, June 5, several members of the USEC and Portsmouth plant management teams met with NRC representatives near Chicago to provide information regarding several apparent violations of our requirements. We discussed these major issues:

Maintenance mechanics installed an autoclave isolation valve actuator upside down. Engineering did not identify adequate testing, and Operations did not observe that the valve did not operate correctly.

Operations and Chemistry did not communicate adequately to prevent violating TSR requirements for handling a uranium deposit.

Engineering, Operations and Maintenance did not communicate clearly resulting in inadequate testing of autoclave isolation valve control air systems.

The plant potentially exceeded HEU possession limits. (Note that this will likely result in no violation).

Enforcement conferences provide the NRC additional information to determine if violations are significant enough to warrant civil penalty. Whether we receive a civil penalty or not, it is clear that all of the issues, with the exception of the one on HEU possession limits, resulted from less than high quality work. Managers and staff personnel spent days gathering

information, determining causes and corrective actions, and packaging the data so the NRC could better understand the issues.

Even without civil penalties, the cost of enforcement conferences is high. Enforcement conferences divert management and employee attention from achieving other important work. We should be asking ourselves, "How can we prevent future enforcement conferences and potential civil penalties?" "How can we establish NRC confidence in the quality of our operations?" "How can we reduce costs and ensure our future success?"

Producing high quality work is the key to operational success at the Portsmouth plant. High quality work is achieved by following procedures and correcting or generating procedures if procedures are inadequate. High quality work is a result from establishing and maintaining clear communications with each other. High quality work is realized when work processes are thought through and then followed up to assure that the expected results are achieved.



*Morris Brown*

### Lockout/Tagout update

1998 Self Study Guides are available through the Plant Training department. The Lockout/Tagout (LOTO) Self Study Guide (SSG) was developed as refresher training required for all LOTO Authorized Employees and LOTO Issuing Authorities. The SSG contains information from 1997 LOTO lessons learned. Copies can be obtained through your OTR (Organizational Training Representative), Technical Trainer, or by contacting Gwen Priode at ext. 4742. (Linda Cole)

### Game tickets available for June 11

Tickets are available to Lockheed Martin employees and their dependents for the Chillicothe Paints home baseball game against the Ohio Valley Redcoats on Thursday, June 11, at the VA Memorial Stadium in Chillicothe.

LMUS is sponsoring a "Children's Hospital Night" for this game. Children who were admitted to Children's Hospital during 1997-98 have been invited to participate in pre-game activities beginning at 6:30 p.m. at the stadium. A corporate contribution to Children's Hospital will be presented by Lockheed Martin during pre-game activities.

McDonalds will also be distributing souvenir cups to the first 500 people in the park.

The Chillicothe Paints provided approximately 100 tickets free of charge for our use during this night. Expenses incurred as a result of attending the game are the responsibility of the ticket holders. Tickets for the June 11 game are available on a first-come, first-served basis and will be distributed in groups of four. Game time is 7:05 p.m. Contact Barb Bowling, Public Affairs, on ext. 2863. Tickets must be picked up no later than NOON on June 11. (Bryant Lybrook)

### Blood drive scheduled

The Bloodmobile will be at the plant on June 18 from 11 a.m.-5 p.m. and again on June 19 from 7 a.m.-1 p.m. in the X-102 Cafeteria. To register for an appointment, please call Barbara Bowling at ext. 2863. Walk-ins are welcome.

### LMUS Ethics Officer

Ron Wetherell

897-2006

Corporation: 1-800LMETHIC

The Chillicothe Gazette  
June 3, 1998  
Page 3A

### Commission to meet with A-plant officials

The Nuclear Regulatory Commission will meet Friday with United States Enrichment Corporation for a pre-decisional enforcement conference on apparent violations at the Piketon uranium enrichment plant.

Topics for discussion will be the corporation's failure to control components with uranium deposits, inadequate maintenance, testing and operation of safety valves on equipment and exceeding the possession limit of some enriched uranium.

Commission officials said such a conference does not mean a violation has occurred or enforcement action will take place. Rather, the purpose is to discuss apparent violations, their causes and safety significance.

Any enforcement action would take place at a later date, officials said.